


# PRESSURE DROP CHARTS

Pex Tubing Pressure Drop at 60° F (16° C)



## Pex Tubing Pressure Drop at 120° F (49° C)

